



## CASIO SMT NOZZLE

Part Number	Description
P2	CASIO 3300 SMT NOZZLE $\phi$ 1.2/ $\phi$ 0.4
P7	CASIO 3300 SMT NOZZLE $\phi$ 3.0/ $\phi$ 1.0
NO. 04	CASIO 3300 SMT NOZZLE $\phi$ 0.8/ $\phi$ 0.5
NO. 05	CASIO 3300 SMT NOZZLE $\phi$ 1.2/ $\phi$ 0.85
NO. 06	CASIO 3300 SMT NOZZLE $\phi$ 1.6/ $\phi$ 1.0
NO. 07	CASIO 3300 SMT NOZZLE $\phi$ 3.0/ $\phi$ 2.3
NO. 21	CASIO 3300 SMT NOZZLE $\phi$ 0.8/ $\phi$ 0.5
M1	CASIO 7000 SMT NOZZLE $\phi$ 1.5/ $\phi$ 0.45
M2	CASIO 7000 SMT NOZZLE $\phi$ 1.0/ $\phi$ 0.4
M7	CASIO 7000 SMT NOZZLE $\phi$ 3.0/ $\phi$ 1.0
M06	CASIO 7000 SMT NOZZLE $\phi$ 1.6/ $\phi$ 1.0
M07	CASIO 7000 SMT NOZZLE $\phi$ 3.0/ $\phi$ 2.3
M31	CASIO 7000 SMT NOZZLE $\phi$ 5.0/ $\phi$ 2.5
M32	CASIO 7000 SMT NOZZLE $\phi$ 7.0/ $\phi$ 4.0
M33	CASIO 7000 SMT NOZZLE $\phi$ 10.3/ $\phi$ 7.0
M34	CASIO 7000 SMT NOZZLE $\phi$ 12.3/ $\phi$ 9.0
M35	CASIO 7000 SMT NOZZLE $\phi$ 14.3/ $\phi$ 11.0
M21	CASIO 7000 SMT NOZZLE $\phi$ 0.8/ $\phi$ 0.5
M22	CASIO 7000 SMT NOZZLE $\phi$ 1.2/ $\phi$ 0.85
M23	CASIO 7000 SMT NOZZLE $\phi$ 2.0/ $\phi$ 1.6